

SECRET**ACTION COPY****3**

P 131638Z MAR 66

FM NPIC

TO DIA

BT

25X1

SUBJ: SUMMARY COMMENTS CONCERNING THE 11 BU Q MISSIONS EVALUATED

BY NPIC.

REF: S-W134/XX-2, 23 FEBRUARY 1966

SUBJ: SUMMARY COMMENTS CONCERNING THE 11 BU Q MISSIONS EVALUATED

1. THE FOLLOWING IS A SUMMARIZATION OF FACTORS AFFECTING IMAGE QUALITY OF BU Q MISSIONS EVALUATED BY NPIC.

2. RANDOM PARTIAL VEILING OF THE VEHICLE WINDOWS BY CONDENSATION, FROST OR ANOTHER SUBSTANCE APPEARS AS THE MAJOR IMAGE DEGRADATION IN A MAJORITY OF THE MISSIONS. OCCASIONALLY ENTIRE MISSIONS WERE AFFECTED.

3. THE DENSITY OF THE ORIGINAL NEGATIVES IS ADEQUATE TO SLIGHTLY THIN. IT IS FELT THAT AN EXPOSURE INCREASE OF FROM ONE-HALF TO ONE F-STOP WOULD HAVE IMPROVED ALL MISSIONS. IN ADDITION, THE ORIGINAL NEGATIVES ARE OF LOW CONTRAST. THIS IS LIKELY DUE TO A COMBINATION OF THE SLIGHT UNDEREXPOSURE, HAZE CONDITIONS AND THE AFOREMENTIONED WINDOW VEILING.

4. BANDING DUE TO UNEVEN SLIT TRAVEL IS EXPERIENCED ON ALL MISSIONS, ALTHOUGH NOT AFFORDING A MAJOR DEGRADATION OF THE IMAGERY. SUCH INTERRUPTED SHUTTER TRAVEL USUALLY INDICATES A "CLEANING" OR FINE TUNING OF THE SYSTEM IS IN ORDER.

5. STANDARDIZATION OF THE INFORMATION CONTENT OF THE WRITE-IN DATA BLOCK WOULD BE HELPFUL. SUGGESTED ENTRIES ARE: SORTIE/ MISSION NUMBER, DATE, CAMERA UNIT NUMBER, AND VEHICLE NUMBER. SHUTTER SPEED (I.E., SLIT NUMBER REFERENCED TO A SHUTTER SPEED) AND F-STOP FOR MISSION WOULD BE OF VALUE.

6. PROCESSING OF THE NEGATIVES CAUSED LITTLE IF ANY DEGRADATION. NO SIGNIFICANT DIFFERENCE WAS NOTICED IN THE PROCESSING FROM THE TWO PROCESSING SITES. THE DUPLICATE POSITIVES WERE PRODUCED AT A CONTRAST LEVEL SATISFACTORY FOR INTERPRETATION. IT IS FELT, HOWEVER, THAT IF THE INITIAL CAUSE FOR THE LOW CONTRAST ON THE NEGATIVES IS CORRECTED THIS WOULD LEAD TO PHOTOGRAPHY OF HIGHER QUALITY.

GP-1

SECRET

-- END OF MESSAGE --

DECLASS REVIEW by NIMA/DOD

SECRETGROUP 1
Excluded from automatic
downgrading and
declassification



22601-8

USEAS Cable Routing Slip

To		Initials
	PMO/SIEB	<i>[initials]</i>
	Ch/SIEB	
1	Dep Ch/SIEB	<i>[initials]</i>
	Ch/Systems A Section	
2	Ch/Systems B Section	<i>2K</i>
3		<i>3B</i>
	Ch/SPS	
	Ch/Micro-D Section	
	SIEB Secretary	

OUT CABLE
Comments:
CHECK CONTENT

25X1